


I . Sketch Drawing



II . Parts List

Index No.	Parts Name	Part No.	Index No.	Parts Name	Part No.
	TW - 3.5		17	Cross-recessed flat head machine screw	SC516
1	Case	3001		Cable set	3015
2	Ratchet	3002	18	Cable	-
3	Cross-recessed flat head machine screw	SC614	19	Thimble	-
			20	hook	-
	Hanger set	3004	21	Safe-lock	-
4	Hanger	-	22	Aluminium lock	-
5	Hanger stopper	-	23	collar	3016
6	Hanger spring	-	24	shock absorber	3017
7	Button-head rivet	-	25	Cable set bolt	PH1/8
8	Hanger shaft	3005	26	Stopper	3018
9	Button-head rivet	RR318		TW-3	
10	Spindle	3007	12	Spiral spring	3009
11	Drum	3008	15	cover	3012
13	Drum cover	3010		TW-5	
14	Cross-recessed flat head machine screw	SC512	12	Spiral spring	5009
16	Flat-toothed lock washer	WT5	15	cover	5012